

5- Condition 1: The "ZERO"

When the sum total of all the weight on the scale
4% of the maximum capacity of the scale.

(4% = 80g, where capacity is 200g 2kg when the capacity is 5kg)

The LCD will show '0 g' every time you press Z / T.
The icon '0' will be shown in the lower left corner
of the LCD,

Indicating that the function 'ZERO' is active.
Hi capacity. weight remains unchanged.

Condition 2: The "TARA"

When the sum total of all the weight on the scales
> 4% of the maximum capacity of the scale.


(4% = 80g where capacity is 2kg, 200g when the capacity is 5kg)

The LCD will show '0 g' every time you press Z / T. The icon 'TARA' will be shown in the lower left corner of the LCD indicating that the function 'TARA' is active.

High capacity. Weight is reduced by the total weight of all loads.

Under this condition:

Pressing Z / T, you can see the total weight of all cargo placed on the scale. If you want even more cargo, just press Z / T to reset the LCD readout to '0' again




6- AUTO OF

Automatic shutdown occurs if the display shows '0' or show the same weight reading 2 minutes.



7- MANUAL OFF

To maximize battery life, always press ON / OFF
To turn off the scale after use.



8- WARNING INDICATORS

1. Replace the battery with a new one.
 2. Too much weight in the balance. Remove some weight to avoid damaging the balance.
Hi capacity, weight shown in the balance.



9- TARA

Tare Weight OZ: Ounce
-: Negative value g: Grams
O: Zero Weight kg: Kilogram
1b: Pounds

CLEANING AND CARE

1. Clean the scale with a damp cloth. DO NOT immerse the balance in the water or use chemical cleaners / abrasives.
 2. All plastic parts should be cleaned immediately after coming into contact with fats, spices, vinegar and spicy or highly seasoned foods. Avoid contact with acidic citrus juices.
 3. Always use the scale on a firm, flat surface. DO NOT use on a carpet.



Manual de Operación



Gracias por elegir los productos PUNKTAL. Para confirmar un correcto funcionamiento y por su seguridad, por favor lea este manual cuidadosamente antes de poner este aparato en uso y guárdelo para futuras referencias.

SÓLO PARA USO DOMÉSTICO

INSTRUCCIONES DE USO / Español



1- BATERIA

1 X 9V (no incluida)




2- PARA CAMBIAR LA BATERIA

Remueva la cubierta del compartimiento de la batería y coloque la batería nueva sobre la placa. Por favor fíjese de que coincida la polaridad.



3- PARA USAR LA BALANZA

1. Por favor coloque la balanza sobre una superficie firme y plana.
2. Coloque un bowl (si lo usa) sobre la balanza antes de encender la unidad.
3. Presione y suelte el botón ON/OFF para encender la unidad.
4. Espere hasta que la unidad muestre '0' antes de comenzar a pesar.



5- Condición 1: Función "CERO"

Cuando la suma total de todo el peso en la balanza = 4% de la capacidad máxima de la balanza. (4% = 80g; cuando la capacidad es de 2kg: 200g cuando la capacidad es de 5Kg) El LCD mostrará '0g' cada vez que presione Z/T. El ícono 'TARA' se mostrará en la esquina inferior izquierda del LCD Indicando que la función 'TARA' esta activa. La capacidad Máx. de peso se reduce debido al peso total de todas las cargas.

Bajo esta condicion:

Presionando Z/T, puede ver el peso total de toda la carga colocada en la balanza. Si desea pesar mas carga, solo presione Z/T para reiniciar la lectura del LCD en '0' nuevamente.




4- PARA CONVERTIR UNIDADES DE PESO

La balanza cuenta tanto con el sistema de medidas Métricas (kilogramos, gramos) y Británico (libras onzas), usted puede presionar UNIT para pasar entre los dos sistemas durante el proceso de pesaje.

Funcion "CERO" o "TARA"

Para pesar diferentes cargas consecutivamente sin retirarlas de la balanza. Coloque primero la carga en la balanza, se lee el peso. Presione el botón para reiniciar La lectura del LCD '0' antes de añadir la carga siguiente. Usted puede repetir esta operación.




6- APAGADO AUTOMATICO

El apagado automático ocurre si el display muestra '0' o muestra la lectura del mismo peso durante 2 minutos.



7- APAGADO MANUAL

Para maximizar la duración de la batería, presione siempre ON/OFF Para apagar la balanza después de usarla.



8- INDICADORES DE ADVERTENCIA

1. Cambie la batería por una nueva
2. Demasiado peso en la balanza.
Retire algo de peso para evitar dañarla. La capacidad Máx. de peso se indica en la balanza.



9- TARA:

Peso en tara	OZ : Onzas
-: Valor Negativo	g : Gramos
O: Cero Peso	kg : Kilogramos
1b: Libras	

LIMPIEZA Y CUIDADO

1. Limpie la balanza con un paño ligeramente húmedo. NO sumerja la balanza en el agua ni use agentes limpiadores químicos/abrasivos.
2. Todas las partes plásticas deben limpiarse inmediatamente después de haber entrado en contacto con grasas, especias, vinagre y alimentos altamente condimentados o sazonados. Evite el contacto con jugos cítricos ácidos.
3. Use siempre la balanza sobre una superficie firme y plana. NO la use sobre una alfombra.

INSTRUCTIONS FOR USE / English



1- BATTERY

1 x 9V (not included)



2- CHANGING THE BATTERY

Remove the cover of the battery compartment and put the new battery on the cookie plate. Please note that matches the polarity.



3- USING THE SCALE

1. Please place the scale on a firm, flat surface.
2. Place a bowl (if used) on the scale before turning the unit.
3. Press and release ON / OFF to turn the unit.
4. Wait until the unit shows '0' before you even start.



4- CONVERT TO UNITS OF WEIGHT

The scale has both metric system (kilograms, grams) and British (pounds, ounces) UNIT you can press to switch between the two systems during the weighing process.

Function "ZERO" or "TARA"

Despite running for different loads without removing the burdens of the scale. First place the load on the scale, read the weight. Press the button to restart The LCD read '0' before adding the next charging. You can repeat this operation.